

- to do:
0. add accelerometer. See sparkfun component re:pull ups
 1. connect nav pins to uC
 2. connect mosfet to uC
 3. set led values and resistors (pps, fix, vbat, vcc)
 4. connect rx/tx output to uC and figure out how that'll work in the package
 - 4.5. test pps w/LED on breakout board to make sure it works
 5. make parts list

AREF used for analog reference voltage. Not connected in this circuit.

